



X-TYPE

DATE 06/04

XT501-17

SERVICE

TECHNICAL BULLETIN

Inability To Open/Close Luggage
Compartment Lid – Actuator Binding –
Revised Actuator Available

MODEL 2002-04 MY
X-TYPE

VIN C64502-E07750

Issue:

Some 2002-04 MY X-TYPE vehicles, within the above VIN range, may exhibit a condition where the user cannot open or close the luggage compartment lid manually or using the key or luggage compartment button.

Temperature and humidity changes can affect the internal components of the luggage compartment lid actuator, causing the actuator to bind.

Action:

In case of a customer complaint of the above condition, install a modified luggage compartment lid latch actuator. Refer to Workshop Manual, section: 501-14, SRO 76.19.25.

Global Technical Reference (GTR):

Dealer Access: <https://hub.franchise.jaguar.com>

Internet access: <http://www.jaguartechno.com>

Parts Information:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Luggage compartment lid actuator (with interior release handle) - North America	C2S 38222	1

Warranty Information:

Description	SRO	Time	Causal Part Number
Install a new luggage compartment lid actuator	76.19.11	0.3 hrs.	C2S 21273

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR RETAILER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

